



OPTIMIZATION OF ASSEMBLY GAP TOLERANCE USING MONTE CARLO METHOD AND SELECTION OF OPTIMAL TOLERANCE METHOD

¹Siva Kumar B, ²Balasubramanyam N, ³A.Sreenivasulu Reddy

¹Masters Student, ²PHD Scholar, ³A. Sreenivasulu Reddy

¹Department of Mechanical Engineering,

¹Sri Venkateswara University, Tiruapti, India

Abstract: The tolerancing concept is essential in part design process. It describes a relation between the many stages of the design and manufacturing activities. In this paper, tolerance models were developed to estimate required tolerance gap of selected assembly parts using python programming. The Monte Carlo Method is selected and using Uniform and Normal Distributions for finding required tolerance gap for given assembly.

Index Terms - Part Assembly, Tolerance Gap, Monte Carlo Method, Python.

I. INTRODUCTION

Tolerance refers to the allowed variation in measurements derived from the base measurement. Tolerances are divided into three categories [1]: Unilateral, Bilateral and Compound tolerances. Unilateral tolerances consist of two limit dimensions that are simply above or below the normal size, whereas bilateral tolerances consist of two limit dimensions that are both above and below the nominal size [1]. Compound tolerances are a combination of more than one form of tolerance; the multiple types of tolerances can include angular, lateral, and other sorts of tolerances. For this work, the bilateral tolerances are taken into account. Gaps would be created while assembling the parts of an assembly; the Monte Carlo method is used to optimize that gap tolerance and is implemented in Python [3].

- An infinite number of assembly part tolerances and gap tolerances are generated within the tolerance range by optimizing the tolerances [2].
- Tolerances of different models are compared each other and represents optimal method [1].

II. METHODOLOGY

In order to obtain the 'n' sample of random values of each part and gap tolerances of part assembly, Monte Carlo method is used, which involves the probability distribution to generate random values of assembly parts [2]. To generate random values, this work considers Normal and Uniform distributions and those methods are implemented in the Python programming. The Monte Carlo method is used for finding optimal solutions. By adopting this methodology, the low possibility of getting errors in assembly occurred [4].




Fig1. Monte Carlo Algorithm

The obtained results from the normal distribution and uniform distribution are observed and compared, between the two methods the optimal method selected for generating ‘n’ sample of random values of tolerances of the assembly.

III. EXPRESSION FOR UNIFORM AND NORMAL DISTRIBUTIONS

(i) Uniform distribution

Uniform distributions are probability distributions in which all events are likely equal. The probability density function [3],

$$f(x) = \begin{cases} \frac{1}{b-a} & \text{for } a \leq x \leq b \\ 0 & \text{for } x < a \text{ or } x > b \end{cases}$$

Where ‘a’ is minimum value and ‘b’ value is maximum value

$$\text{Mean } (\mu) = \frac{(a+b)}{2}$$

$$\text{Standard Deviation } (\sigma) = \sqrt{\frac{(b-a)^2}{12}}$$

(ii) Normal distribution

Normal distribution (Gaussian distribution) is a symmetric probability distribution around the mean, indicating that data near the mean occur more frequently than data far from it. The probability density function [4],

$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} e^{-\frac{1}{2}\left(\frac{x-\mu}{\sigma}\right)^2}$$

$$\text{Mean } (\mu) = \frac{(a+b)}{2}$$

$$\text{Standard Deviation } (\sigma) = \frac{\text{Tolerance}}{3}$$

IV. CASE STUDY

The figure 4.1 is considered and the methodologies described in this work are used to generate the tolerance for the assembly gap [5].




Fig 4.1 Mechanical Motor Assembly

Part 1(A) and 2(B) = 10 ± 0.005
 Part 3(C) = 8.95 ± 0.011
 Part 4(D) = 56 ± 0.015
 Part 5(E) = 9 ± 0.007
 Part 6(F) and 7(G) = 3 ± 0.005
 Part 8(H) = 100 ± 0.017

Here, the dimensions of part 1, 2, 4,5,6,7 are fixed dimensions and 3 and 8 are variable dimensions and their values calculating by using tolerancing methods.

4.1 MODELING OF TOLERANCE BY USING MONTE CARLO METHOD

$$\text{Gap} = H - (A+B+C+D+E+F+G) \quad (\text{eq.1})$$

$$\text{Total Tolerance (TT)} = 3 * \sqrt{(SD_A)^2 + (SD_b)^2 + \dots + (SD_H)^2} \quad (\text{eq.2})$$

$$\text{Gap}_{(\text{max})} = H - (A+B+C+D+E+F+G) + \text{TT} \quad (\text{eq.3})$$

$$\text{Gap}_{(\text{min})} = H - (A+B+C+D+E+F+G) - \text{TT} \quad (\text{eq.4})$$

According to the eq.1, eq.2, eq.3 and eq.4, the following table represents Mean, Standard deviation and Total Tolerance of Normal distribution and Uniform distribution for each part of the mechanical assembly.

Table1. Values of Mean and Standard deviation

PART	NORMAL DISTRIBUTION		UNIFORM DISTRIBUTION	
	MEAN (μ)	SD (σ)	MEAN (μ)	SD (σ)
A	10	0.0016	10	0.0028
B	10	0.0016	10	0.0028
C	8.95	0.0036	8.95	0.0063
D	56	0.0050	56	0.0086
E	9	0.0023	9	0.0040
F	3	0.0016	3	0.0028
G	3	0.0016	3	0.0028
H	100	0.0056	100	0.0098
Total Tolerance	0.0280		0.3240	
Gap_(max)	0.3740			
Gap_(min)	0			

These values are taken as inputs for generating the tolerances of each part and gap tolerance of the mechanical assembly in the Python according to the Normal distribution and Uniform distribution of Monte Carlo method.

V. RESULTS AND DISCUSSIONS

According to the chapter III, the python code for the Tolerancing Methods of Monte Carlo Method is implemented and the assembly tolerances are generated by using Normal Distribution and Uniform Distribution and their results are,

Output of the Uniform distribution

Table2. Tolerance Values of the assembly parts

```

List of the random numbers of part-A :
RANDOM VALUES 1   RANDOM VALUES 2   RANDOM VALUES 3   RANDOM VALUES 4
0      9.999656      9.996441      10.000785      10.001392
1      9.999416      9.999342      10.002058      9.997893
2      10.001789      10.000599      10.000029      9.997775
3      10.002193      10.001998      9.998240      10.001246
4      10.002297      10.000901      10.004041      10.002364
5      10.003487      9.997433      10.001477      9.999157
6      10.000914      9.998799      10.000344      10.001352
7      9.999557      9.996574      9.999667      9.999856
8      10.001031      10.001988      9.998069      9.999726
9      9.998851      10.001353      9.999716      10.001349


List of the random numbers of part-B :
RANDOM VALUES 1   RANDOM VALUES 2   RANDOM VALUES 3   RANDOM VALUES 4
0      9.999320      9.999986      10.001486      9.999952
1      10.002902      10.000241      9.998559      10.001477
2      9.999853      9.997744      9.998897      9.997652
3      9.998798      10.002488      10.001370      10.000805
4      9.999781      10.002234      9.997632      9.998384
5      10.001448      9.998174      9.997497      9.999654
6      9.997101      10.004268      9.999529      10.003766
7      10.000673      9.998080      9.998243      10.000180
8      10.000828      10.000179      10.002350      10.001947
9      10.000994      10.000878      10.001245      10.001341
  
```

Similarly, random values generated for part-C to part-H and the Gap tolerances of assembly,

Table 3. Tolerance values of the Gap

Gap :	RANDOM	VALUES 1	RANDOM	VALUES 2	RANDOM	VALUES 3	RANDOM	VALUES 4
0		0.044846		0.067387		0.048068		0.041381
1		0.047303		0.053572		0.033874		0.055084
2		0.044421		0.049727		0.037238		0.075008
3		0.047350		0.028257		0.060032		0.043299
4		0.031725		0.053757		0.064774		0.053111
5		0.060848		0.048421		0.048607		0.060496
6		0.043630		0.051837		0.048499		0.041735
7		0.053991		0.058472		0.032252		0.055657
8		0.037513		0.061448		0.055302		0.044282
9		0.051521		0.038852		0.054005		0.033443

Graph



The graph represents the relation between the Gap on X-axis and no. of samples on Y-axis and grey vertical lines represent lower limit and upper limit of gap. The samples outside of grey vertical lines are failures.

Output of the Normal distribution

Table4. Tolerance Values of the assembly parts

List of the random numbers of part-A :								
	RANDOM	VALUES 1	RANDOM	VALUES 2	RANDOM	VALUES 3	RANDOM	VALUES 4
0		9.998154		10.000955		9.999342		10.004538
1		10.004507		9.995699		10.001203		9.995915
2		9.996037		9.998187		10.001552		9.999555
3		10.002420		10.003879		9.998409		10.001128
4		10.000202		10.001693		10.002582		10.002520
5		9.996737		9.996574		10.001243		9.995903
6		10.002300		9.995277		10.004225		9.998242
7		10.001001		9.999753		9.998898		9.995621
8		10.000377		9.999915		10.000210		10.004247
9		10.004839		9.996455		9.998029		10.000825


List of the random numbers of part-B :								
	RANDOM	VALUES 1	RANDOM	VALUES 2	RANDOM	VALUES 3	RANDOM	VALUES 4
0		9.998869		9.998361		9.997954		9.995241
1		9.999078		9.995465		10.002567		9.999037
2		10.001395		9.995966		9.997386		10.001937
3		9.998392		9.997545		9.995504		10.001812
4		9.995836		10.002574		10.002284		9.995832
5		10.004261		10.003403		10.003413		9.997449
6		9.998431		10.002518		10.000481		9.999496
7		9.995472		10.002736		10.003321		10.003220
8		10.003426		10.002352		10.001342		9.997838
9		10.000189		10.002725		10.000412		10.004206

Similarly, random values generated for part-C to part-H and the Gap tolerances of assembly,

Table 3. Tolerance values of the Gap

Gap :	RANDOM	VALUES 1	RANDOM	VALUES 2	RANDOM	VALUES 3	RANDOM	VALUES 4
0		0.051925		0.022732		0.065607		0.063674
1		0.043316		0.030390		0.042026		0.053369
2		0.029901		0.025986		0.058736		0.039508
3		0.056028		0.014480		0.076607		0.048720
4		0.036657		0.086656		0.043816		0.054748
5		0.051212		0.059440		0.030503		0.033895
6		0.067492		0.006559		0.061152		0.074807
7		0.043243		0.042211		0.058699		0.049119
8		0.057554		0.046010		0.032875		0.034287
9		0.058019		0.035598		0.033337		0.070574

Graph



The graph represents the relation between the Gap on X-axis and no. of samples on Y-axis

VI. COMPARISON BETWEEN THE UNIFORM AND NORMAL DISTRIBUTIONS

The mean and standard deviation are the inputs for uniform and normal distributions. And also, lower and upper limits are considered as inputs for uniform distribution. By comparing the values of both the distributions, it is observed that the rejection rate of the assembly of normal distribution is less than the uniform distribution. It is found that the estimated values of tolerance gap are very low in normal distribution.

VII. CONCLUSION

The optimal tolerance gaps were estimated for given assemblies to minimize the defects like rework and rejection of the machine parts. Values of both distributions are compared; So that the normal distribution is considered as optimal tolerance method.

REFERENCES

- [1] The Engineering Post – Measuring Instruments « Tolerances: Types and difference between unilateral and bilateral tolerances » 13 May 2020
- [2] Hassani Abdeddalem, « Computer Aided Tolerancing Based on Analysis and Synthetizes of Tolerances Method » 16 December 2008.
- [3] Math Works, « Uniform Distribution (Continuous) » 22 November 2019.
- [4] Weisstein, Eric W « Normal Distribution » Mathworld.wolfram.com Retrieved August 15, 2020.
- [5] Madhavi Reddy G V, Sreenivasulu Reddy A « Assembly Gap Tolerance Calculation using ANFIS and cost Function Optimization » 11 February 2022.